YAMAHA CORPORATION

October 5, 2000

Release Notes for DS-XG VxD Driver Version 4.12.01.2019

1. Environment

1.1 OS Support:

Windows 95/98/98SE

1.2 Language Support:

English/Japanese/French/Italian/German/Spanish/Portugues-Brazilian/
Swedish/Korean/Simplified Chinese/Traditional Chinese

1.3 Hardware Support:

YMF744B(DS-1S)/YMF754(DS-1E)

2. File Information

2.1 Driver Version

YDSXG.DRV	4.12.01.2019
YDSXG.VXD	4.12.01.2019
YDSXGDK.VXD	4.12.01.2019
DS1.CPL	4.12.01.2019
DSPOWEXT.DLL	4.12.01.2019
YDSLG.DRV	4.12.01.1230
YDSLG.VXD	4.12.01.1230
VSVL.VXD	4.00.1009
AUDIO3D.DLL	4.12.01.1005
CRLDS3D.DLL	4.12.01.2000
CRLDS3D.VXD	4.12.01.1035
DSXAPLIB.DLL	4.00.00.2008
DSLAUNCH.EXE	4.00.00.2008
DSMIXER.EXE	4.00.00.2008

2.2 Files

AUDIO3D.DLL	786,432	00-03-22	10:05
CRLDS3D.DLL	765,952	00-03-06	20:00
CRLDS3D.VXD	196,585	00-03-06	10:35
DS1.CPL	294,192	00-09-29	20:19
DS1BRA.HLP	25,232	00-03-23	20:00
DS1ENG.HLP	21,519	00-03-23	20:00
DS1FRE.HLP	25,460	00-03-23	20:00
DS1GER.HLP	24,985	00-03-23	20:00
DS1ITA.HLP	24,766	00-03-23	20:00
DS1JPN.HLP	20,441	00-03-23	20:00
DS1KOR.HLP	22,076	00-03-23	20:00
DS1SCH.HLP	15,576	00-03-23	20:00
DS1SPA.HLP	26,166	00-03-23	20:00
DS1SWE.HLP	24,737	00-03-23	20:00
DS1TCH.HLP	18,812	00-03-23	20:00
DSLAUNCH.EXE	286,720	00-06-29	20:08
DSPOWBRA.HLP	14,182	00-03-23	20:00
DSPOWENG.HLP	9,604	00-03-23	20:00
DSPOWEXT.DLL	172,032	00-07-03	20:19
DSPOWFRE.HLP	14,004	00-03-23	20:00
DSPOWGER.HLP	12,997	00-03-23	20:00
DSPOWITA.HLP	13,722	00-03-23	20:00
DSPOWJPN.HLP	9,052	00-03-23	20:00
DSPOWKOR.HLP	12,131	00-03-23	20:00
DSPOWSCH.HLP	8,287	00-03-23	20:00
DSPOWSPA.HLP	14,244	00-03-23	20:00
DSPOWSWE.HLP	13,494	00-03-23	20:00
DSPOWTCH.HLP	10,274	00-03-23	20:00
DSXAPLIB.DLL	57,344	00-06-16	20:08
DSXMIXER.EXE	376,832	00-06-29	20:08
VSVL.VXD	890,471	98-07-24	22:29
YDSLG.DRV	47,712	00-03-13	12:30
YDSLG.VXD	37,659	00-03-13	12:30
YDSXG.DAT	2,417,445	98-04-03	9:54

YDSXG.DRV	176,512	00-07-03	20:19
YDSXG.VXD	1,019,478	00-07-03	20:19
YDSXGDK.VXD	5,744	00-07-03	20:19
YDSXGS0.INF	21,643	00-07-04	20:19
YDSXGDK.INF	1,543	00-07-04	20:19

3. Updates (Changes from the previous release)

---

1. Fixed the Mixer issue occurred when the VxD driver is enabled from a disabled status. When the driver is disabled and then enabled while the Mixer is running, the updated information of the Mixer was not reflected to the Mixer application.
2. Supports ICH2
3. Updates the hyperlink of the Sensaura URL on the CPL applet.
4. YAMAHA Mixer update (4.00.00.2008)

   WinME support.

   . Supports to get information of YAC3REN.AX.

   . Removed the Multimedia Menu when the OS is WinME.

   . Added the WindowsMediaPlayer7 Menu when the OS is WinME.

   . Supports the WindowsMediaPlayer7 Menu when the windowsMediaPlayer7 is installed on the non-WinME OS.

   . Removed the CD player Menu when the OS is WinME.

   Korean Translation

   . Added a missing Korean translation in the Help.